CONTRACTOR PRODUCTION REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)						DATE Jul 10, 2018		
CONTRACT NO TITL		TLE AND LOCATION	REPORT NO	REPORT NO				
N40080-17-C-0505	R	Repairs to Paint & Blast Shop, Bldg. 339NS, NSA Annapolis				032		
CONTRACTOR Lansdowne Construction			SUPERINTENDENT Fredrick K. Gei					
AM WEATHER		PM WEATHER			MAX TEMP (F) MIN TEMP (F)			
		WORK PERI	FORMED TODAY			Add	Del	
Schedule Activity No	WORK LOCATION AND I	DESCRIPTION	EMPLOYER	NUMBER	TRADE		HRS	
64; 65; 70; 71 Bldg 339NS Weld Shop 3-3, 3-4, 3-7, 3-8, 3-9		o - Installing UH	BPI Mechanical	2	Pipefitter; Pipefitter Apprentice	r	20	
					TOTAL WORK HOURS ON JOB	_		
JOB SAFETY	WAS A JOB SAFETY MEETING HEL (If YES attach copy of the meeting WERE THERE ANY LOST TIME ACC (If YES attach copy of completed	g minutes) CIDENTS THIS DATE?	_	YES NO		20		
(If YES attach statement or check WAS HAZARDOUS MATERIAL/WA	G/SCAFFOLD/HV ELEC/HIGH WORK/HAZI list showing inspection performed) .STE RELEASED INTO THE ENVIRONMENT?		_	YES NO	HOURS FROM PREVIOUS REPORT TOTAL WORK HOURS FROM START OF CONSTRUCTION	460		
Schedule	of incident and proposed actions.) LIST SAFETY ACTIONS TAKEN TODAY/SAFETY INSPECTIONS CONDUCTED SAFETY REQUIREMENTS HAVE BEEN MET					Add	Del	
Activity No 64; 65; 70; 71	Proper wearing and use of PPF: working from a lift and proper operation and tie-off requirements: wearing of a							
Schedule	ODAY TO BE INCORPORATED IN JOB (IND	DICATE SCHEDULE ACTIVITY	NUMBER)			Add	Del	
Activity No	Submittal #	al # Description of Equipment/Material Received						
	+							
CONSTRUCTION AND PLANT FOUIP	MENT ON JOB SITE TODAY. INDICATE HO	OURS USED AND SCHEDULE	ACTIVITY NUMBER.					
Schedule			Description of Construction Equipment Used Today (incl Make and Model)				Add Del	
Activity No	Owner	Description of Construc	tion Equipment Used Today (incl M	lake and Model)		H	ours Used	
						Add	Del	
Schedule	REMARKS							
4; 65; 70; 71 UH 3-3, existing in General Shop Bay (Room 103), relocated to Paint Spray Bay (Room 101).								
<u> </u>	Do not have access to UH 3-5, 3-6 in General Shop Bay (Room 103) due to Navy equipment blocking access to these two UHs.							
Cannot access Sanding Bay (Room 102) due to blasting/painting ops by Navy contractor blocking entrance outside of this room. Need access for scissor lift to enter Room 102.							ce	
	Waiting on delivery of steam traps.							
					Jul 10, 2018			
CONTRACTOR/SUPERINTENDENT DATE								